



Underside of top

Center Post (hollow)

Tolerance adjustors – as the center post is pushed into a hole, these tolerance adjustors would be squeezed by the pushing into the hole.